

FIG. 1




FIG. 2 (a)





FIG. 2 (b)






FIG. 3

FIG. 4




FIG. 5




FIG. 6





FIG. 7



10/550275

8/13

FIG. 8

INK OUTFLOW CAUSED BY REPEATED CYCLE OF 50-DEGREES RISE




FIG. 9






FIG. 10



10/550275

11/13

FIG. 11



10/550275

12/13

FIG. 12




FIG. 13




FIG. 14

